Date Inspected: 6/1/2011

Inspected By: Brett Gilmore,
Brad Lammers

GATES	EXERCISED	FLAP	COMMENTS
			ALL SLIDE GATES OPENED COMPLETELY PER WILLIAMS ENGINEERING
			all flap gates excavated except c11
C-1			under water
C-3			filled with slurry and abondoned due to subdivision
C-5	xx		Dual slide and flap gate (under water)
C-7			under water
C-9	x		under water
C-11		x	
C-13			under water
C-15			under water
C-17	x		under water
C-19	x		under water
C-21	x		under water
C-23	x		under water
C-25	xx		dual slide and flap gate (under water)
C-27			under water
C-29			under water
C-31		x	
C-33		x	
C-35			u

Date Inspected: 6/1/2011

Inspected By: Brett Gilmore,
Brad Lammers

GATES	EXERCISED	FLAP	COMMENTS
C-2		x	
C-4			
C-6			
C-8			
C-10		x	
C-12		x	
C-14		x	
C-16			under water
C-18			storm sewer outlet from Ross Park/S. 5th (under water)
C-20	x		under water
C-22	x		under water
C-24		x	
C-26			under water
C-28			under water
C-30			under water
C-32		x	under water
C-34			under water
C-36		x	
C-38			under water
C-40			under water
C-42			under water
C-44			under water
C-46			under water
C-48			Second Street wetlands outlet (under water)